

TABLE OF CONTENTS

Section	Page No.
COVER PAGE	1
1.0 BACKGROUND	1
1.1 PLATE TECTONICS AND EARTHQUAKES IN SOUTHERN CALIFORNIA	1
1.2 THE POTENTIAL FOR FAULT RUPTURE AT THE GROUND SURFACE	1
1.3 BLIND THRUST FAULTS OF THE ELYSIAN PARK FAULT SYSTEM.....	2
1.4 MINOR FAULTS ABOVE THE BLIND THRUSTS.....	2
2.0 METHODS	3
2.1 INTRODUCTION	3
2.2 EXPOSING AND MAPPING THE STRATA AND FAULTS AT THE SURFACE	3
3.0 FINDINGS	4
3.1 INTRODUCTION	4
3.2 SUMMARY OF FAULT LOCATIONS AND SIZES	4
3.2.1 <i>Three Categories of Faults</i>	5
3.3 DIRECTION OF SLIP ON THE FAULTS	5
3.4 AMOUNT OF TOTAL SLIP ON THE FAULTS IN 3 MILLION YEARS	6
3.5 ACTIVITY OF THE FAULTS	10
3.6 ESTIMATION OF SLIP PER EARTHQUAKE ON THE FAULTS	11
3.7 FAULTS ON THE WESTERN LEG OF THE BLC PROPERTY.....	12
4.0 CONCLUSIONS AND INTERPRETATION OF GEOLOGIC RISK	13
4.1 THE PRINCIPAL MINOR FAULT ZONE	13
4.2 THE LESSER FAULTS.....	13
4.3 THE WESTERN PORTION OF THE PROPERTY.....	13

FIGURES, TABLE and PLATE (all Figures at the Back of the Text)

FIGURE 1:	SITE LOCATION AND REGIONAL FAULT MAP OF SOUTHERN CALIFORNIA	
FIGURE 2:	GEOLOGIC MAP AND CROSS-SECTION OF DOWNTOWN LOS ANGELES AREA	
FIGURE 3:	TYPICAL EXPOSURE OF PUENTE FORMATION IN TRENCHES AT THE BELMONT LEARNING CENTER	
FIGURE 4:	OBLIQUE AERIAL PHOTO OF BELMONT LEARNING CENTER SHOWING THE LOCATION OF TRENCHES EXCAVATED FOR THIS STUDY	
FIGURE 5:	FAULT LOCATION MAP	
FIGURE 6:	EXAMPLES OF CATEGORY A AND CATEGORY C FAULT ZONES	
FIGURE 7:	PHOTOGRAPHS OF CATEGORY A, B AND C FAULT ZONES	
FIGURE 8:	EXAMPLES OF A CATEGORY B FAULT ZONE FROM THE SOUTH WALL OF TRENCH 9	
FIGURE 9:	BLOCK DIAGRAM OF OFFSET BEDDING	
FIGURE 10:	ISOPACH MAP OF CATEGORY C FAULT ZONE IN TRENCH 5	
FIGURE 11:	GEOLOGIC MAP OF DOWNTOWN DISTRICT SHOWING LOCATION OF BELMONT LEARNING CENTER	
FIGURE 12:	STEREO PAIR OF AERIAL PHOTOGRAPHS TAKEN IN 1941 SHOWING THE BELMONT LEARNING CENTER	
FIGURE 13:	FAULT CONSTRAINTS MAP	
FIGURE 14:	Estimated Slip-per-Earthquake on Faults Beneath Academy House 2	
TABLE 1:	STRIKE-SLIP AND DIP-SLIP DISPLACEMENTS CALCULATED FROM FAULT AND BEDDING GEOMETRY AND APPARENT SEPARATION MEASURED IN TRENCH EXPOSURES.....	8
PLATE 1:	FAULT LOCATION MAP	IN POCKET

APPENDICES

- Appendix A: References
- Appendix B: Trench Logs
- Appendix C: Aerial Photograph